



												
	<b>T-type</b>	<b>4</b>	<b>4A</b>	<b>Mil Dot</b>	<b>FFT</b>	<b>Cross Hair</b>	<b>SVD</b>	<b>SVDL</b>	<b>TL</b>	<b>4L</b>	<b>4AL</b>	<b>4NL</b>
P3,5x20	+											
P4x32 P4x32M P4x32L	+		+	+			+	+	+		+	+
P6x42 P6x42L	+		+	+		+	+	+	+		+	+
P8x48 P8x48L	+	+	+	+	+	+	+	+		+	+	+
P8x56 P8x56L P8x56LF		+	+		+					+	+	+
P10x42F P10x42FL		+	+		+	+	+	+		+	+	+
P12X50 P12x50L P12x50LF		+	+	+	+	+				+	+	
PV 1,2-6x24 PV 1,2-6x24L		+	+							+	+	+
PV2-10x48 PV2-10x48L		+	+	+	+	+				+	+	+
PV2-10x52 PV2-10x52L		+	+	+	+	+				+	+	